

**CONSTRUCTION PHASE HAZARD IDENTIFICATION**  
In accordance with the Construction (Design & Management) Regulations 2015.

**CDM**  
The hazard sign is a notification to other designers and contractors of foreseeable exceptional risks resulting from the design activities carried out by HLM Architects Ltd, which are beyond those reasonably expected to be identified by a competent person, as defined in the Construction (Design & Management) Regulations 2015 - Regulation 9 & 10 and Industry Guidance for Designers (Section 4) published by the CITB (2015).

DRAWING REVIEWED	YES
EXCEPTIONAL RISKS / RISK CONTROL MEASURES	see warning triangle none or see warning triangle

**Rooflight Key - from below**

- Existing rooflight in existing roof, no works indicated above amended rooms only
- Make good or replace rooflight on existing roof/ opening (asbestos to be removed or encapsulated as required)
- New rooflights and openings to existing roofs
- Proposed rooflight on proposed roof



666

Refer to landscape drawings

Existing Sportspitch

Project	The Piggott School	Title	GROUND FLOOR (PHASE 2) SCIENCE PROPOSED
Client	WOLKINGHAM BOROUGH COUNCIL	Scale @ A1	1:100@A1
Date	11.11.2022	Drawn	AL
Checked	KP	Revisions	S4 STAGE APPROVAL
Revision No.	PGT-HLM-P2-00-DR-A-00152	Revision	P04

Notes Check all dimensions on site. Do not scale from this drawing. Report any discrepancies and omissions to HLM Architects. This Drawing is Copyright©

Scale: 1:50, 1:500, 1:100

Scale: 5 M, 50 M, 10 M

HLM Architects  
Wool + Tailor Building  
Fifth Floor  
10-12 Aile Street  
London E1 8DE

www.hlmarchitects.com  
T: +44 (0) 20 7921 4800  
F: +44 (0) 20 7921 4850  
london@hlmarchitects.com

This page is intentionally left blank